

DART AEROSPACE LTD

Reason for Change: CAR18-265, CAR19-300, CAR18-274, CAR19-306

Documents Released:
DSI 9808 Rev. B, IIN-D350-822 Rev. I, ICA-D350-822 Rev. 7, D4943 Rev. D, D5721 Rev. A, SB19-1 Rev. A, DSI 9826 Rev. A

URF: 19-639

PARTS MUST COMPLY ☒ **X**

PREVIOUS PARTS SATISFACTORY ☐

#	Engineering Actions	Reqd	Resp	Notes	Complete
5	Required Documents/Drawings/Item ID's Under Review (URF)	Y	VS	URF 18-871, URF 19-639	19.04.02
6	Update Master Document List (MDL)	Y	VS	MDL-D350-822 Rev. R	19.04.02
7	Update Document Record (DR)	N			
8	Update Product Compatability Matrix	N			
9	Notify TC / FAA of Change (eg. ICA, 8110-3)	N			
10					

Description / Action:
-D350-822-011 @CHG 006, D350-822-013 @CHG 005, DSI 9826-011 @CHG 001
-Create/Update BOMS and Routes
- close CAR 18-265, CAR 19-300, CAR18-274, CAR 19-306
- Add SB19-1 Rev. A and DSI 9826 Rev. A to Product Specifications and Dart Website
-Ensure we have a copy of all Pall Drawings listed on MDL-D350-822 Rev. R on the Dart network
-Update D350-822-011/-013 kits in stock per IIN-D350-822 Rev. I
- Scrap D4943-1 in stock or rework to D4943 Rev. D
URF 18-871 and 19-639 closed.

Date: 12/4/12